

M. SHRINAGESH
PUBLIC RELATIONS MANAGER

Lr.No.CMWSSB/P&A/PRL/Area V/Depot.75/2009 Dated: 10.12.2009

To

The Editor
The New Indian Express
Plot No.29, Door No.83,
2nd Main Road
Ambattur Industrial Estate
Chennai-600 058.

Sir,

Sub: CMWSSB – Letter by Thiru V. Sundararajan,
Virugambakkam published in your newspaper - Reply
furnished - Reg.

Ref: Publication in "The New Indian Express", Chennai
dated 16.11.2009.

....

Please refer to the letter written by Thiru V. Sundararajan,
Virugambakkam resident of Saibaba Colony near Elango Nagar regarding sewer
overflow at Saibaba Colony.

In this regard, it is informed that during the recent rains, the entire
Saibaba Colony was flooded with rain water since it was a low lying one. Further,
there is no storm water drain available in this stretch and the local residents are
letting out the rain water into the sewerage system by opening the manholes.
Since the manholes are already in surcharge condition, the sewage from the
manholes get mixed with the rain water and it stagnates in this stretch.
Appropriate remedial measures have been initiated.

PUBLIC RELATIONS MANAGER

pdfMachine

A pdf writer that produces quality PDF files with ease!

Produce quality PDF files in seconds and preserve the integrity of your original documents. Compatible across
nearly all Windows platforms, if you can print from a windows application you can use pdfMachine.

Get yours now!